

TO BE FILLED BY THE INSPECTING OFFICER

Name of School : SREEKRISHNAPURAM CENTRAL SCHOOL, KATAMPAZHIPURAM

1. Name of Officer : AMBILIN, Assistant Engineer, L.S.G.D.
Katampazhipuram GP
2. Location : SREEKRISHNAPURAM CENTRAL SCHOOL,
Education Dist : Ottapalam
3. Period for which Certificate is issued : Academic Year 2022-2023
4. Types of building : RCC Three storied building 3468.20 m²
- Ground Floor
- Class room : 10Nos-6.10m x 6.10m x 3.70m
Class room : 1No-10.58m x 6.10m x 3.70m
Lab : 1No-10.58m x 6.10m x 3.70m
Class room : 1No-6.10m x 6.44m x 3.70m
Class room : 1No-25.12m x 6.10m x 3.70m
Server Room : 1No-3.08m x 2.24m x 3.70m
Store Room : 1No-3m x 6.10m x 3.70m
Reception : 1No-6.24m x 6.10m x 3.70m
- First Floor
- Class room : 15Nos-6.10m x 6.10m x 3.70m
Class room : 1No-6.10m x 9m x 3.70m
Class room : 1No-12.44m x 6.10m x 3.70m
Class room : 1No-6.24m x 6.10m x 3.70m
Sports room : 1No-3.08m x 2.24m x 3.70m
- Second Floor
- Class room : 10Nos-6.10m x 6.10m x 3.70m
Lab : 2Nos-12.44m x 6.10m x 3.70m
Library : 1No-6.24m x 6.10m x 3.70m
Sports room : 1No-3.08m x 2.24m x 3.70m
5. Name of defect if any : NIL
- (a) Foundation and basement : NIL
- (b) Superstructure : NIL
- (c) Doors and windows : NIL
- (d) Wood work wrought and put up : NIL
- (e) Roof : NIL
- (f) Flooring : NIL
- (g) Miscellaneous : NIL
6. Any other major defect noticed which will render the building unsafe if any manner : No
7. Whether maintenance work have been done properly : YES
8. Whether structure is sound for conducting classes : YES, Structure is sound for conducting classes under normal wind and weather condition

Note : (1) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

(2) Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 30.05.2022 and found fit to conduct classes for the period for the reason stated above.

Place: Katampazhipuram
Date : 30.05.2022

Signature:
Designation:

Ambilin
30/5/22
Assistant Engineer
LSGD Section
Katampazhipuram Grama Panchayat

PLAN SHOWING THE EXG. SCHOOL BUILDING OF A RSY NO. 1003, BLOCK: 77, WARD: 1 AT
 KATAMPAZHIPURAM 1 VILLAGE & PANCHAYATH, OTTAPPALAM TALUK, PALAKKAD DT.

FIRST FLOOR PLAN



Amith

Assistant Engineer
 LSGD Section
 Katampazhipuram Grama Panchayath